


PowerCurtain CL-920C4 Motor with INSTEON 2444-222



Note: Since Power is supplied by Insteon 2444-222, PowerCurtain Remote Control will not work.

If PowerCurtain Remote Control is required to work, PowerCurtain model CL-920C6 Motor will do the job.